

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DD534
SW
1/2-1
0.822 mi.
4341 ft.
CONEY ISLAND MAINT GARAGE
3026 WEST 25TH ST
BROOKLYN, NY
Site 6 of 6 in cluster DD

NY Spills **S112228662**
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: CONEY ISLAND MAINT GARAGE
Address: 3026 WEST 25TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1208483 / 2013-11-17
Facility ID: 1208483
Facility Type: ER
DER Facility ID: 425816
Site ID: 471545
DEC Region: 2
Spill Cause: Storm
Spill Class: C4
SWIS: 2401
Spill Date: 2012-10-29
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2012-11-02
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-11-02
Spill Record Last Update: 2013-11-17
Spiller Name: Not reported
Spiller Company: HURRICANE SANDY
Spiller Address: Not reported
Spiller Company: 999
Contact Name: BILL KLEIN
DEC Memo: "09/19/2013 - V. Brevdo This is Hurricane Sandy related spill (1208483) that was unassigned until today. Attention to this was brought up by NYCDDC during today's quarterly meeting. Alex Zhitomirsky has three other spill cases on Coney Island Maintenance Garage: 0550468; 1113400; and 1206177. V. Brevdo discussed this with Jeffrey Vought of Spill Prevention and Response in the absence of Randall Austin. Jeff did not have objections against Section B (Alex Zhitomirsky) managing this spill, given Alex has three other spill cases on this address/site. Spill Case is assigned to Alex Zhitomirsky effective today 09/19/2013. VB 11/17/13 TJD Site inspection - met on site with NYC Parks Maintenance Supervisor (Robert Sangroni). Location is the NYC Parks Department Coney Island Garage. Interview with Mr. Sangroni reveals the following: - Underground tank system was empty and in process of replacement at time of storm. - Spill was associated with discharge from (55) gallon drum of gasoline onsite for contractor (Franklin Company) purposes as part of tank replacement project. - Area sustained significant flooding and sand deposits associated with Hurricane Sandy - Franklin Company reported to have cleaned spill and removed an unknown volume of contaminated sand to the satisfaction of NYC Parks Department. - A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

3K FO AST located in basement/crawlspace was inservice prior to storm
- tank is strapped down - piping was dislodged from tank during storm
but no reported discharge occurred. - 3K AST is Out of Service since
storm - unknown if tank has been pumped - not leaking - no petroleum
odors interior or exterior of structure was evident at time of
inspection. Unknown if tank still contains contaminated product from
storm impacts. - A 1K FO AST temp tank is currently staged on
sidewalk for on site consumption. - Facility has a pending contract

to convert to gas heat and remove AST in basement. - New UST's were
installed and operating since January 2013 include 1K Gasoline & 2K
Diesel - Perimeter of structure and basement/crawlspace floor (sand)
appear clean and free of residual petroleum impacts based upon visual
and olfactory inspection. No further action is required associated
with reported Hurricane Sandy spill at this property. Spill is closed
and cross-referenced to existing open spill numbers (1206177) at this
site (referenced in DEC remarks dated 9/19/13)."

Remarks:

"total 600 gallons - cleanup crew on scene"

All Materials:

Site ID: 471545
Operable Unit ID: 1221402
Operable Unit: 01
Material ID: 2220045
Material Code: 0021
Material Name: transmission fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 471545
Operable Unit ID: 1221402
Operable Unit: 01
Material ID: 2220047
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 471545
Operable Unit ID: 1221402
Operable Unit: 01
Material ID: 2220046
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name:

CONEY ISLAND MAINT GARAGE

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Address: 3026 WEST 25TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1208483 / 2013-11-17
Facility ID: 1208483
Facility Type: ER
DER Facility ID: 425816

Site ID: 471545
DEC Region: 2
Spill Cause: Storm
Spill Class: C4
SWIS: 2401
Spill Date: 2012-10-29
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2012-11-02
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-11-02
Spill Record Last Update: 2013-11-17
Spiller Name: Not reported
Spiller Company: HURRICANE SANDY
Spiller Address: Not reported
Spiller Company: 999
Contact Name: BILL KLEIN
DEC Memo: "09/19/2013 - V. Brevdo This is Hurricane Sandy related spill (1208483) that was unassigned until today. Attention to this was brought up by NYCDDC during today's quarterly meeting. Alex Zhitomirsky has three other spill cases on Coney Island Maintenance Garage: 0550468; 1113400; and 1206177. V. Brevdo discussed this with Jeffrey Vought of Spill Prevention and Response in the absence of Randall Austin. Jeff did not have objections against Section B (Alex Zhitomirsky) managing this spill, given Alex has three other spill cases on this address/site. Spill Case is assigned to Alex Zhitomirsky effective today 09/19/2013. VB 11/17/13 TJD Site inspection - met on site with NYC Parks Maintenance Supervisor (Robert Sangroni). Location is the NYC Parks Department Coney Island Garage. Interview with Mr. Sangroni reveals the following: - Underground tank system was empty and in process of replacement at time of storm. - Spill was associated with discharge from (55) gallon drum of gasoline onsite for contractor (Franklin Company) purposes as part of tank replacement project. - Area sustained significant flooding and sand deposits associated with Hurricane Sandy - Franklin Company reported to have cleaned spill and removed an unknown volume of contaminated sand to the satisfaction of NYC Parks Department. - A 3K FO AST located in basement/crawlspace was inservice prior to storm - tank is strapped down - piping was dislodged from tank during storm but no reported discharge occurred. - 3K AST is Out of Service since storm - unknown if tank has been pumped - not leaking - no petroleum odors interior or exterior of structure was evident at time of inspection. Unknown if tank still contains contaminated product from storm impacts. - A 1K FO AST temp tank is currently staged on

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

sidewalk for on site consumption. - Facility has a pending contract to convert to gas heat and remove AST in basement. - New UST's were installed and operating since January 2013 include 1K Gasoline & 2K Diesel - Perimeter of structure and basement/crawlspace floor (sand)

appear clean and free of residual petroleum impacts based upon visual and olfactory inspection. No further action is required associated with reported Hurricane Sandy spill at this property. Spill is closed and cross-referenced to existing open spill numbers (1206177) at this site (referenced in DEC remarks dated 9/19/13)."

Remarks:

"total 600 gallons - cleanup crew on scene"

All Materials:

Site ID: 471545
Operable Unit ID: 1221402
Operable Unit: 01
Material ID: 2220045
Material Code: 0021
Material Name: transmission fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 471545
Operable Unit ID: 1221402
Operable Unit: 01
Material ID: 2220047
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Site ID: 471545
Operable Unit ID: 1221402
Operable Unit: 01
Material ID: 2220046
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported